

Two-Way Linear Actuator Connectors

for One-Axis System, Aluminum, Unequal Bore Dimensions d1 / d2

SPECIFICATION

Identification no.

No. 2: With 2 stainless steel socket cap screws DIN 912

Aluminum Powder coated Black, RAL 9005, textured finish **SW** Sleeve bearing

Sleeve bearing Plastic (PTFE)

Socket cap screws DIN 912 Stainless steel AISI 304

Hex nuts DIN 985 Stainless steel AISI 304 Self-locking via polyamide ring



Two-way linear actuator connectors GN 133.1 are based on two-way connector clamps. The additionally provided mounting holes are used to connect to the drive key of a linear actuator. Bores with the designation ${\bf G}$ are equipped with sleeve bearings.

With the screw locations $\mathbf{z_i}$, the play of the guide bore d_i can be adjusted or the linear actuator connectors can be clamped after adjustment.

For quick clamping without tools, the socket cap screws can be replaced by the adjustable hand levers GN 911 (see page 1874) listed in the table as accessories.




ACCESSORY

- Adjustable Hand Levers GN 911 (see page 1874)

TECHNICAL INFORMATION

- Plastic Characteristics (see page A2)
- Stainless Steel Characteristics (see page A26)



GN 133.1-Without sleeve bearing

Description	d1 - d2 without sleeve bearing	d3 Mounting screws on the drive key	k1 Clamping length	k2 Clamping length	l1	I2	l3	m	z1 Screw location	z2 Screw location	Accessory Recom. hand lever GN 911 for z1 I4	Accessory Recom. hand lever GN 911 for z2 I4	42
GN 133.1-B30-B18-2-SW	B30 - B18	M 4	40	36	81.5	40	26	27	M8-25	M6-20	63 78	45 63	133
GN 133.1-B50-B30-2-SW	B50 - B30	M 6	65	59	122	65	40	45	M10-50	M8-25	78 92	63 78	450

GN 133.1-With sleeve bearing

Description	d1 - d2 with sleeve bearing	d3 Mounting screws on the drive key	k1 Clamping Iength	k2 Clamping length	l1	I2	13	m	z1 Screw location	z2 Screw location	Accessory Recom. hand lever GN 911 for z1 I4	Accessory Recom. hand lever GN 911 for z2 I4	Δ'Δ
GN 133.1-G30-B18-2-SW	G30 - B18	M 4	40	36	81.5	40	26	27	M8-25	M6-20	63 78	45 63	133
GN 133.1-G50-B30-2-SW	G50 - B30	M 6	65	59	122	65	40	45	M10-50	M8-25	78 92	63 78	450